

KYDEX® 6200 LTR: Thermoforming and Fabrication Guidelines

TB - 143

Introduction

KYDEX® 6200 LTR sheet is a specially formulated for the mass transit industry for interior applications where SMP800C compliance is required in addition to FRA flame and smoke requirements outlined in 49 CFR 238 Appendix B/ NFPA 130.

For a toxicity compliant sheet, KYDEX® 6200 LTR has excellent forming and fabrication properties, which results in uniform wall thicknesses and crisp detail. KYDEX® 6200 LTR is capable of forming to deep draws while maintaining a relatively high resistance to hot tearing. KYDEX® 6200 LTR can be easily trimmed, cut and machined with conventional woodworking and sheet metal shop tools.

Forming Guidelines

- Typical heater settings (percentage timers) are 30% – 50% top heaters and 50% - 70% bottom heaters.
- Two sided (sandwich) heaters are recommended for forming KYDEX® 6200 LTR.
- The most frequent problem is trying to heat the sheet too quickly, particularly on the primary surface.
- Cycle times will vary depending on the oven conditions, type of heating elements, and cooling efficiency.
- Initially, it is better to rely on the sheet appearance during heating than on fixed cycle times.
- Forming temperatures – Guidelines: (Try not exceed 400°F (204°C) surface temperature).
360 - 385°F (182 - 196°C) for 0.080" to 0.125" (1.5mm to 3.2mm).
385 - 400°F (196 - 204°C) for > 0.125" (3.2mm)
- Ideally, the core sheet temperature should be within 10°F of the surface temperature.

Approximate Heating Times

Sheet Thickness	Time (seconds)
1.5mm (0.060")	70 - 80
2.0mm (0.080")	90 - 100
2.4mm (0.093")	100 - 110
3.2mm (0.125")	135 - 145
4.0mm (0.156")	165 - 180
4.7mm (0.187")	195 - 210
5.59 mm (0.220")	230 - 245

- Heating times will vary with heater type and heater set percentages.
- Due to the increased density, KYDEX® 6200 LTR will take about 10% longer to heat than typical KYDEX® sheet grades.
- Drying is generally not required for KYDEX® 6200 LTR except if stored in high humidity conditions or if the material is older than 3 months. Material not stored in original moisture proof packaging may have to be dried sooner than three months. If the material needs to be dried, dry at 150°F (65°C) using the following guidelines:
2.0mm (0.080") - 10 hours
3.2mm (0.125") - 16 hours
5.6mm (0.220") – 20-24 hours
- For additional thermoforming information and troubleshooting guidelines see Technical Briefs 116 and 117.
- *Pressure forming is an alternative technique to standard thermoforming, which allows for tighter radii, better detail, and more uniform wall thickness.*

KYDEX, LLC
ISO 9001 and 14001 Certified

Customer Service
6685 Low St, Bloomsburg, PA 17815 USA
Phone: 800.325.3133, +1.570.389.5810
Outside the US: +1.570.389.5814
Fax: 800.452.0155, +1.570.387.7786
Email: info@kydex.com

Technical Service
Phone: 800.682.8758
Fax: +1.570.387.8722
Outside the US: +1.570.387.6997
Email: techservice@kydex.com

www.kydex.com

KYDEX® 6200 LTR: Thermoforming and Fabrication Guidelines

TB - 143

Design Criteria

- The minimum recommended radius for simple vacuum forming is generally equal to the thickness of the starting sheet. In addition, an easy to form radius is 4 times the thickness of the starting sheet.
- Mold Shrinkage for male molds is 0.4% - 0.6% and female molds, 0.5% - 0.7%.
- It is recommended that mold design be reviewed in areas where typically thin areas are present.
- As with any decorative surface, thermoforming will distort the design so draw depths will be limited.

Storage Recommendations

KYDEX recommends that for long-term storage of KYDEX® 6200 LTR, following the instructions on Technical Brief 151 will help protect the sheets during handling, minimize moisture absorption and help in keeping the sheets clean.

Fabrication Guidelines

KYDEX® 6200 LTR Sheet can easily be cut and machined with conventional woodworking and sheet metal shop tools; special tools designed for plastic fabrication are not necessary but would result in cleaner edges.

Cracking or stress whitening of the material is a result of inducing too much stress into the part during the routing or cutting process. Ramping in slowly will ease the cutter in and prevent the part from stress fracturing or stress whitening. If stress whitening occurs; it can be removed easily by applying a slight amount of heat from a heat gun. Cold forming or bending is not recommended.

Gluing Guidelines

An adhesive should not be selected solely based on bond strength information. Factors such as the environmental resistance, cure speed, thermal resistance, and substrate types will play a critical role in determining the best adhesive for a specific application.

KYDEX® 6200 LTR can be adhered to itself and other thermoplastics using some of the more popular adhesives: 2-part acrylics, cyanoacrylates, and solvent cements. Although surface treatment is not necessary for a good bond, surface roughening is a simple, low cost method of increasing the bondability of KYDEX® 6200 LTR. All surfaces should be cleaned with isopropyl alcohol prior to bonding regardless of adhesive used.

2-part Acrylics like Devcon Plastic Welder, Lord 406/19, or 3M DP 8010 will offer best overall adhesion to the most substrates.

Cyanoacrylates, and solvent cements (standard PVC cements) will work best in small, smooth surface areas where a structural adhesive is not needed. These adhesive are very poor gap fillers. These also tend to flash off quickly and have a very rapid cure rate so working time is very limited.

**As with any application, contact the adhesive manufacturer for additional adhesive recommendations, technical information and application directions. Always test for suitability.*

KYDEX, LLC
ISO 9001 and 14001 Certified

Customer Service
6685 Low St, Bloomsburg, PA 17815 USA
Phone: 800.325.3133, +1.570.389.5810
Outside the US: +1.570.389.5814
Fax: 800.452.0155, +1.570.387.7786
Email: info@kydex.com

Technical Service
Phone: 800.682.8758
Fax: +1.570.387.8722
Outside the US: +1.570.387.6997
Email: techservice@kydex.com

www.kydex.com

KYDEX® 6200 LTR: Thermoforming and Fabrication Guidelines

TB - 143

Mechanically Fastening

If bonding is not practical for a specific application, KYDEX® 6200 LTR can also be mechanically fastened following a few simple guidelines.

To minimize cracking and stress whitening, the use of nylon or rubber washers is recommended in combination with oversized holes. Oversized holes, by 1/16" (1.5 mm) will also help prevent part buckling from expansion and contraction due to temperature changes. In addition, large headed fasteners are recommended to prevent the fastener heads from pulling through the sheet in higher stress areas.

Cleaning

Cleaning the primary side of KYDEX® 6200 LTR, which is the glossier/textured side, is very similar to cleaning standard KYDEX® sheet grades therefore the suggestions found on Technical Brief 114 can be followed.

In Addition:

- Do not use cloths containing grit or abrasive particles, or kitchen scouring compounds to clean KYDEX® 6200 LTR primary surface.
- Strong solvent-based graffiti removers may leave a slightly dull finish if left on the surface too long, if multiple applications are required, or if considerable scrubbing is needed.
- As with any decorative surface, thermoforming will distort the design so draw depths will be limited.

KYDEX, LLC

ISO 9001 and 14001 Certified

Customer Service

6685 Low St, Bloomsburg, PA 17815 USA
 Phone: 800.325.3133, +1.570.389.5810
 Outside the US: +1.570.389.5814
 Fax: 800.452.0155, +1.570.387.7786
 Email: info@kydex.com

Technical Service

Phone: 800.682.8758
 Fax: +1.570.387.8722
 Outside the US: +1.570.387.6997
 Email: techservice@kydex.com

www.kydex.com

Because we cannot anticipate or control the many different conditions under which this information and our products may be used, we do not guarantee the applicability of the accuracy of this information or the suitability of our products in any given situation. Users should conduct their own tests to determine the suitability of each product for their particular purposes. Data in the physical property table represents typical values and are to serve only as a guide for engineering design. Results are obtained from specimens under ideal laboratory conditions. Right to change physical properties as a result of technical progress is reserved. THE PRODUCTS DISCUSSED ARE SOLD WITHOUT WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE, EITHER EXPRESSED OR IMPLIED, EXCEPT AS PROVIDED IN OUR STANDARD TERMS AND CONDITIONS OF SALE. Buyer assumes all responsibility for loss or damage arising from the handling and use of our products, whether done in accordance with directions or not. In no event shall the supplier or the manufacturer be liable for incidental or consequential damages. Also, statements concerning the possible use of our products are not intended as recommendations to use our products in the infringement of any patent. Consult local code and regulatory agencies for specific requirements regarding code compliance, transporting, processing, recycling and disposal of our product. Product not intended for use as a heat resistant surface. Texture, product grade and other conditions may cause variations in appearance.

This information supersedes all previously published data.